# i-Measuring camera)

VGA high-definition measuring Digital camera

2.0 M pixel Direct to LCD screen

# Leading Innovation>>>

Experiencing on screen measurement Just a few mouse clicks, no computer require

c-mount VGA camera

Camera YOU NEED for Measurement



Model: i-measure

#### i-measure VGA camera

Package contents:

• i-Measure VGA camera

100-240V power supply adaptor
 Calibration scale


PS2 mouse


System requirements:


VGA cable & Monitor

i-Measure

## On screen measurement camera









FC (E

Product by Seekscope

#### **Features:**

o 1/3" Color CMOS

Resolution 1600x1200 Monitor resolution and frame rate

1600x1200: 23 fps 1680x1050: 26.5fps 1440x900 : 28 fps 1366x768 : 29 fps 1280x1024: 25 fps 1024x768 : 23 800x600 : 23 fps fps

800x600 : 23 tps

Scan Method : Progressive scanning
Exposure control : Auto / Manual
White Balance : Auto / Manual
Color : Color, B/W, Sepia, Negative
Monitor interface : VGA
Storage : support USB disk 256M-32G
PS/2 Mouse control
Power 5V DC 100-240V power supply

### Performance capabilities:

Support Flip & Freeze image, 1/2 freeze image for comparison

Support to create Line&Mark generator
-12 groups movable cross hair, horizontal line, vertical line

- create 3 groups of movable circle mark&size - 360° circle scale

- 2 adjustable angle lines

- movable screen ruler & scale adjustable

- arrow mark

Measurement

- Calibration support and 5 groups memorized

- Linear distance,

- Circle diameter , circumference and area

- Rectangular length, width, perimeter and area

- Polygon's perimeter and area

- Circle Center distance

- Ellipse's perimeter and area

- Arc's radian and length

- Angle

www.isscope.com